

Under Review Notification

Raised By: VANESSA MOREL

Product #: DART TOOLING AGUSTA

Date: 17.10.20

Product Name: PULLER ASSY, HUB

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RBW6205G25331-3G-3	RBW6205G25331-3G REV 1	Y	Y	N	Y	Y	Y	N	17-629	Rework to prelim new drawing or scrap

Description of Issue: CRITICAL DIMENSION MISSING, CHAMFER MISSING

RBW6205G25331-3G-3 REV B : 0.03 X 45° CHAMFER ADDED, 0.624" +/-0.002" DIMENSION ADDED

Distribution:

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------